

1.6

6	7	8
EC No.	EC Description	DR.
1	/	/

A



B

C

D

E

F



A

B

C


D

E

F

NOTES:

1. Material: Brass C3604;
2. Heat Treatment: None;
3. Surface Treatment: Cleaning;
4. Packaging: PE bag and Carton;
5. Free of burrs and sharp edges;
6. Thread must be checked with Go/No Go Gauge;
7. Unless otherwise specified: ± 0.12 mm and angle $\pm 2^\circ$.



1 2 3 4 5 6 7 8