



1 2 3 4 5 6 7 8

1.6

EC No.	EC Description	DR.
△	/	/



NOTES:

1. Material: Brass C3604;
2. Heat Treatment: None;
3. Surface Treatment: Cleaning;
4. Packaging: PE bag and Carton;
5. Remove all burrs and sharp edges;
6. Thread must be checked with Go/No Go Gauge;
7. Unless otherwise specified; $\pm 0.1\text{mm}$ and angle $\pm 2^\circ$.



1 2 3 4 5 6 7 8